

HABS
DC,
WASH,
336-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

S. Kann & Sons
(Kann's Department Store)
Market Space, between 7th and 8th Sts., NW
Washington
District of Columbia

HABS No. DC-365

Jet Lowe, Photographer April, 1979

DC-365-1	SOUTH FRONT (AFTER FIRE DAMAGE)
DC-365-2	SOUTH FRONT, WESTERN HALF (AFTER FIRE DAMAGE)
DC-365-3	SOUTH FRONT, WESTERN HALF, DETAIL OF WINDOWS (AFTER FIRE DAMAGE)
DC-365-4	SOUTH FRONT, EASTERN HALF (AFTER FIRE DAMAGE)
DC-365-5	SOUTH FRONT, EASTERN HALF, DETAIL OF BURNED SECTION
DC-365-6	SOUTH FRONT AND EAST SIDE (AFTER FIRE DAMAGE)
DC-365-7	NORTH SIDE (AFTER FIRE DAMAGE)
DC-365-8	NORTHWEST CORNER ENTRANCE (AFTER FIRE DAMAGE)
DC-365-9	WEST SIDE (AFTER FIRE DAMAGE)